



SC4947 ASSEMBLY INSTRUCTIONS

- 1.0 TRIM CABLE PER STRIPPING DIMENSIONS.
- 1.1 SLIDE SHRINK TUBE AND CRIMP RING ONTO CABLE.
- 1.2 FLARE BRAID AS SHOWN
- 2.0 SOLDER PIN ONTO CENTER CONDUCTOR.
- 3.0 ASSEMBLE THE CABLE BY PLACING CONNECTOR BODY ON
- 4.0 CRIMP AND HEAT SHRINK TUBE


1.




2.



3.



4.



FAIRVIEW MICROWAVE INC.

ALLEN, TX 75013 WWW.FAIRVIEWMICROWAVE.COM

TITLE

SC4947 ASSEMBLY INSTRUCTIONS

SIZE	CAGE CODE	DWG NO	REV
A	3FKR5	SC4947 AI	--

SCALE	SHEET
-------	-------