

AGANWANI	02/21/2022	INITIAL RELEASE	Α
APPROVED	DATE	DESCRIPTION	REV.





STRIPPING DIMENSIONS

ASSEMBLY PROCEDURE

- STRIP CABLE AS SHOWN AND TIN CENTER CONDUCTOR.
- 2. SOLDER CONTACT TO CENTER CONDUCTOR.
- INSERT CABLE INTO CONNECTOR BODY UNTIL OUTER CONDUCTOR BOTTOMS OUT ON SHOULDER IN CONNECTOR BODY. SOLDER OUTER CONDUCTOR TO BODY.

 $\omega$ 

THESE COMMODITIES, TECHNOLOGY OR SOFTWARE WERE EXPORTED FROM THE UNITED STATES IN ACCORDANCE WITH THE EXPORT ADMINISTRATION REGULATIONS. DIVERSION CONTRARY TO U.S. LAW PROHIBITED.

UNLESS OTHERWISE SPECIFIED LEADING DIMENSIONS ARE INCHES DIMENSIONS IN [] ARE MILLIMETERS.



an INFINITe brand

HITE

