









STRIPPING DIMENSIONS

- NOTES:

 1. CABLE ATTACHMENT:

 OUTER: CRIMP.

 INNER: SOLDER/CRIMP.

 2. CRIMP SIZE REQUIRED:

 FERRULE: .255 [6.48] HEX. CRIMP TOOL.

 CONTACT: .068 [1.73] HEX. CRIMP TOOL.



THESE COMMODITIES, TECHNOLOGY OR SOFTWARE WERE EXPORTED FROM THE UNITED STATES IN ACCORDANCE WITH THE EXPORT ADMINISTRATION REGULATIONS. DIVERSION CONTRARY TO U.S. LAW PROHIBITED.

Fairview Microwave



TIT IE

